Dart Aerospace Ltd. Monday, 1/7/2008 3:38:06 PM Kim Johnston User **Process Sheet** : FWD X-TUBE **Drawing Name** Customer : CU-DAR001 Dart Helicopters Services Job Number : 36619 : 10006 Estimate Number : D2889 Part Number P.O. Number S.O. No. : NA D2889 REV B : 1/7/2008 **Drawing Number** This Issue : N/A Prsht Rev. Project Number : LANDING GEAR **Drawing Revision** First Issue Material Previous Run : 1/14/2008 Each Due Date Qty: 1 Um: Written By Checked & Approved By New Issue 05-10-25 JLM Comment **Additional Product** Job Number: Description: Seq. #: Machine Or Operation: D6005180 Crosstube material 1.0 Comment: Qtv.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Crosstube material Qty Part number Description EC 8-1-8 Fwd Crosstube 1 D2889 BENDING Comment: LANDING GEAR RESOURCE 1 1-Bend D2889 as per Dwg D2889 and Folio FT001 8-1-8 LANDING GEAR RESOURCE 1 3.0 LANDING GEAR 1 Comment: LANDING GEAR RESOURCE 1 1-Deburr and Polish DIMENSIONAL Comment: DIMENSIONAL CHECK HAND FINISHING RESOURCE #1 5.0 HAND FINISHING

Comment: HAND FINISHING RESOURCE #1

Inside and outside of tube

Acid etch and alodine as per QSI 005 4.1

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		·							
Part No	Part No: D389 PAR #: 156 Fault Category: Date: ORIOILI								
	QA: N/C Closed: Date:								

NCR:	SIA	WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section B Action Description	Sign &	Verification Section	Approval Chief Eng	Approval QC Inspector
06 0 QQ	20		"all "	Chief Eng  cletete program from filis  Scrapi destroy  replace aty 1 B 33963  Programs to be werked  an in Accordage with PAR IS	EL 8-1-8	100-01-09	MS 08/61/09	10801-08
			770	on in Acceptance a. In part 13				

NOTE: Date & initial all entries


Monday, 1/7/2008 3:38:06 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: FWD X-TUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 36619 Part Number: D2889 Job Number: Description: Seq. #: Machine Or Operation: INSPECT POWDER COAMPHEMICAL CONVERSION 6.0 QC3 PACKAGING RESOURCE #1 7.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: W/O 36468 FINAL INSPECTION/W/O RELEASE QC21 8.0 Comment: FINAL INSPECTION/W/O RELEASE - 2008 (1 /10 Job Completion


Dart Ae	rospace	e Ltd							
W/O:			W	ORK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						,			
				·					
·						·····			
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	Date:	
					QA: N	I/C Close	d:	_ Date: _	
NCR:			WORK ORE	ER NON-CONFORMAN	NCE (NCF	₹)			
		Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8	Sect	ion C	Chief Eng	QC Inspector

NOTE: Date & initial all entries

DART AEROSPACE LTD		Work Order:	36619
Description: Crosstube Fwd		Part Number:	D2889
Inspection Dwg: D2889	Rev: B		Page 1 of 1

Required Dimension	Min	Max
Height	49.875	50.125
1/2 Span	69.275	69.525
Angle	49	52
Total Span	138.55	139.05





Rev	Date	Change	Revised by	Appr	øved
Α	07.02.06	New Issue	KJ/JM	. ,	~~
		· ·	• ()		

